

Status
Profile Details

### Windows 10 - BIOS

BIOS config for Dell computers

Severity	Time	Device	User	Source	Module	Category	Event	Admin	Event Data
Notice	2/19/2020 8:28 PM	LAP-DEMO	mario.juarez	Device	Devices	Command	Reset Bios Password Confirmed	sysadmin	
Error	2/19/2020 8:28 PM	LAP-DEMO	mario.juarez	Server	Devices	Command	Install Profile Failed	sysadmin	Message Text : com.airwatch.windowsprotectionagent
Error	2/19/2020 8:27 PM	LAP-DEMO	mario.juarez	Server	Devices	Command	Install Profile Failed	sysadmin	Profile : Windows 10 - BIOS

Latitude 5401 | 10.0.17763 | Ownership: Corporate - Dedicated

Summary
Compliance
Profiles
Baselines
Apps
Updates
Content
Location
User
BIOS

#### Security

BIOS Password is Set ?

TPM State Is Enabled ✓

#### Boot

Secure Boot is Enabled ✓

#### Virtualization

CPU Virtualization is Enabled ✓

Trusted Execution is Disabled ⚠

Virtualization IO is Enabled ✓

#### Connectivity

Wireless LAN is Enabled ✓

Cellular Radio is Enabled ✓

Bluetooth is Enabled ✓

#### Storage

SMART Reporting is Enabled ✓

#### Power Management

Primary Battery Charge is configured for Auto Charge ?

Primary Battery Custom Charge Start Limit is 50% ?

Primary Battery Custom Charge Stop Limit is 80% ?

Peak Shift Battery Threshold is 15% ?

Peak Shift is Disabled ⚠

#### System Information

Manufacturer is Dell Inc. ?

Model is Latitude 5401 ?

Asset Tag is FC4V1X2 ?

BIOS Version is 1.0.2 ?

Manufacture Date is 6/24/2019 7:00 PM ?

First Power On Date is 7/23/2019 7:00 PM ?

Battery Health Status is 94% ?

#### System Properties

DCIM\_Battery ?

EstimatedChargeRemaining 99